## MID - Warning Check oil-level appears

**Models:** 

Astra-F 92-98,5, Vectra-B 96-98, Astra-G 98,5-99

**Engines:** 

1.8 1, 2.0 1

**Option:** 

X18XE,X20XEV

Group:

J - Engine

**Troublecode:** 

Non

**Complaint:** 

Wrong Indication

Warning "Check oil-Level" appears too early although the oil-level is correct.

Cause:

Sensor "Oil-Level" responds too early.

## **Production Solution:**

## Special part:

No

## Remedy:

In case of complaint flash improved software on MID. Improved software is available on TIS-CD-ROM 52.

More information for MID programming-refer to the appropriate checking procedure.

If the warning appears again after the programming, a mechanical defect must be assumed. In this case you have to check engine wiring harness, plugs and oil-level sensor.

Labouroperation: TC: Hours: T 8123 70 MID programming 92 0.2hrs

The regular warranty procedure should be used for claiming